VISION OF ENVIRONMENTAL HEALTH:
N-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

12-9-99 AH#6 0-12 Rbrn scl fr sp 12-28 SAB RCL fr ssp 28-60 Rd yl CH/L few common mf sp fr ssp (PS.3)

WNER: _____ APPLICANT: _____
DDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 10-6-99
ROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
OCATION OF SITE: Lot 24 Deer Valley PROPERTY RECORDED: _____
ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
VALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
YPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

#5 THIS ZONE → 0-14 massive fri brn scl; 14-36 mfsab rbrn c/cl fr sp; 36-46 triplet gr cl/cl many brn mottles few ch 2 cinders; 46-60 Rsd fr sp

0.25 25 gpd/sq ft < 36" here

PROFILE	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
		0-6	brn scl	fri					
		6-20	SAB RCL	fr sp-ssp					.3
		20-62	mfsab yr cl/c sp	few dyn 2 fr ss sp mp					= 24 (cs)
		0-22	brn sl/scl fr ssp						
		22-46	rcl many g brn	few dyn mottles — thin layer (4) to (a) required					
		46-60	rbrn L	fr sp					
		0-22	brn scl/cl fr ssp						.25 .25
		22-40	mfsab rbrn c/cl fr-fri sp-ssp	common g brn mottles					
		40-50	mfsab/fsab L fr ssp						
		0-6	massive brn scl						.25 .3
		6-22	SAB RCL/CL	fr ssp					
		22-58	mfsab/fsab yr CH/L common mf sp fr ssp						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ailable Space (.1945)		
stem Type(s)		
LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____