DIVISION OF ENVIRONMENTAL HEALTH:
SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____
ADDRESS: _____ APPLICANT: _____
PROPOSED FACILITY: _____ APPLICATION DATE: _____ DATE EVALUATED: 6-8-99
LOCATION OF SITE: Lot 46, Deer Valley PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed Need more pits. Install 36" min to both

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-11	brn sdl	fr sssp					
		11-17	wk sbk y brn sdl/cl	fr sssp	~24"		esp a.w. depth		(4)
		17-27	sbk/mas R sdl	fi sssp common – many y brn mottles – few dk					
		27-53+	wk fmbk r/cl	fi sp – sssp	few/comp at lower portion of B; drainage mottles not conclusive of SHWT				
2		0-7	brn sdl	fr sssp					.45 .3 >37"
		7-27	sbk brn sdl/cl	fr-fi sp					
		27-38	wk fmbk y brn L	common L sssp					
		38-60	fsl	sso-fsssp					
3	8-1-99	0-13	compacted massive brn sdl	vfr					.25 at least gets better w/depth
		13-22	g wk sbk brn sdl	fr sssp					
		22-41	m-wk sbk brn	fi sp common y brn mottles, few dk					
		41-53	LSCp	fr sssp	Restrictive @ 41-53"		Install @ 36"		
4	8-1-99	0-11	somewhat compacted brn sdl	fr-fi sssp					.15 .025-.3 gets better w/depth
		11-37	SBK brn-R r/cl	fi sp-sssp common y brn mottles					
		37-58+	LSCp/LSCp	fr sssp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____