SION OF ENVIRONMENTAL HEALTH:
SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

WNER: _____ APPLICANT: _____
DDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 10-5-99
ROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
OCATION OF SITE: lot 47 Deer Valley PROPERTY RECORDED: _____
ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
VALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
YPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

NEED one deeper pit

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-19	brn, sdy scl	fr ss/sp—sp					PS .25
		19-28	sdy chy scl/cl	fr ss/sp					
		28-40	wk fsbk ybrn sdy cl/c	common mi/sp fr ss/sp					
		40-57	[illegible]	common mi/sp fr ss/sp					
2		0-21	brn sdy c/c	fr sp					PS .22-.25 @ 21"
		21-37	BC wk fsbk/mas ybrn sdy cl/c	common mi/sp fr ss/sp					.03 + ≥ 32"
		37-53	tan lgt brn sdy L/SL	sp—sp					
3	12-1-99	0-14	brn/ora sdy CL	fr/fi ss/sp					PS .03+ >25"
		14-25	sdy c/cl	fr/fi ss/sp mi/sp					
		25-57	BC L/sp	fr/sp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ailable Space (.1945)		
stem Type(s)		
e LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____