DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 4-30-02
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 21 Fairwinds PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	9%	0-5	gr brsl scl	Sapric					-3
		5-13	Sapric	Hemic					
		13-41	mottled gr-y brn L sap	Hemic/sap					
		41-65	wt mottled gr L sap	fri sap					
2	11%	0-3	gr brn scl						-3
		3-15	sapric	fri sap					
		15-28	mottled L sap	fri sap	Common/sap				
		28-59	wt mottled L sap	fri sap					
3	AH	0-20	sapric	fri sap					-3
		20-29	mottled gr L	fri sap	common/sap				
		29-59	wt mottled gry L sap	fri sap					
4	AH	0-16	sapric	fri sap					-3
		16-35	mottled gr L	fri sap	common/sap				
		35-59	wt mottled gry L sap	fri sap					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

AH #5 0-7 sapric fri sap
7-__ mottled gr L fri sap stp -3
__-__ wt mottled gry L fri sap stp