COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

ER: _____ APPLICANT: _____

RESS: _____ APPLICATION DATE: _____ DATE EVALUATED: Nov 2, 01

OSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

ATION OF SITE: Lot 18 Fair winds PROPERTY RECORDED: _____

ER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

LUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

E OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

must maintain 100' well / septic separation

.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
Pit 18A	0-6	gr brn sl/sc gr	fr	few inf	SAP			.3
	6-27	SAB brn R C	fr sap	few dist				
	27-48	massive gr brn	l/sap fr sap	few dist	L			
18B	0-4	dry massive gr sl/sc gr	fr					.3
	4-19	SAB RC	fi-fr sp/sap					
	19-35	mod SAB R-gr cl	few dist sap					
	35-55	wk fsab massive	fr/l common dist sap					
18C	0-3	dry massive gr l/ns/sl gr	fr					.3
	3-17	SAB RC	fr sp/sap					
	17-53	wk fsab/sg gr cl	fr ss/p common dist sap					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
able Space (.1945)		
n Type(s)		
TAR		

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____