IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System — G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Phillip McCoy DATE 6-30-76 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 70 E TR on Rd # 2359 — Cross 3rd CREEK - MOBILE HOME on LEFT PAST 9 CEDARS TRAILER PARK S. R. No. 2359


SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms _____ No. Bathrooms _____

Garbage Disposal Unit	Yes ( )	No ( )	Character & Porosity of Soil	_____
Auto. Dishwasher	Yes ( )	No ( )	Percolation Rate	Repair
Auto. Wash. Machine	Yes ( )	No ( )	Topography	_____
Site Suitable	Yes ( )	No ( )	Depth to Water Table	_____
			Rock or other impervious formations	_____

Lot Area _____



Plot of System

Size of Tank Existing Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 625 Linear Ft. 250
Depth of Stone in Lines 10"
Water Supply: Individual (✓)
Public ( )

Installed by _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY _____ DATE 6/30/76

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold