VISION OF ENVIRONMENTAL HEALTH:
I-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

156
153

...ER: Glenda Williams APPLICANT: _____
)DRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 6/10/2002
OPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
CATION OF SITE: Bellesda PROPERTY RECORDED: _____
\TER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
'ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
PE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-10" Brn SiL							PS .3
	10"-36" RS/Brn to Brn m-w SiCL w/							
	36-48" RS/Brn to Brn CL w/ few to mod							
	0-6" Brn SiL							PS .3
	6"-36" RS/Brn to Brn m-w SiCL w/ Fe to FR							
	36"-48" RS/Brn to Brn CL w/ few to mod							

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
...ilable Space (.1945)		
...tem Type(s)		
...LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____