DEPARTMENT OF ENVIRONMENTAL HEALTH
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: ____
COUNTY: ____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Howard Wagoner APPLICANT: ____
ADDRESS: ____ APPLICATION DATE: ____ DATE EVALUATED: 7/31/20
PROPOSED FACILITY: ____ PROPOSED DESIGN FLOW (.1949): ____ PROPERTY SIZE: ____
LOCATION OF SITE: ____ PROPERTY RECORDED: ____
WATER SUPPLY: ❑ Private ❑ Public ❑ Well ❑ Spring ❑ Other ____
EVALUATION METHOD: ❑ Auger Boring ❑ Pit ❑ Cut
TYPE OF WASTEWATER: ❑ Sewage ❑ Industrial Process ❑ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL CLASS & LTAF
1		0-6"	Rd/Brn SCL/C						PS .2-.25 to 39"
		6"-17"	Lt Brn	L - Fi					
		17"-32"	Lt/Brn	SCL FS, PE-SE					
		32-48	Lt Brn	SCL/C F S, P, E					
			Chroma 2	Mott's	at 39"				
2		0-12	Rd/Brn SCL/C	SS	SP, SE, FR				PS .2-.25 to 20" Vat 20"
		12-20	Rd/Brn C/SC	SS, P, S-SE, Fi					
		20-24	Rd/Brn C w/Few	Chroma 2 Indic's					
		24"	Lots of Expansive Clay						
3	Unusual Bulge!!?	0-12"	Rd/Brn CL	M-W SBK SS	SP, SE, FR				PS
		12"-24"	Rd/Brn C w/SBK	Many Red Iron Mottles					
		24"-36"	Rd/Brn C/C w/ Indic of Y-/Brn						
		36-48"	Grey	L/SIL					
4		0-4"	Rd/Brn C						Vat 23"
		4"-23"	Grey/Brn	L					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ____
SITE CLASSIFICATION (.1948): ____
EVALUATED BY: ____
OTHER(S) PRESENT: ____