I

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Ruby Glasgow DATE 7/10/87 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 70E, On Rt past Bell Rd

S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes	(✓)	No	( )	Character & Porosity of Soil Clay
Auto. Dishwasher	Yes	( )	No	(✓)	Percolation Rate 2-4
Auto. Wash. Machine	Yes	(✓)	No	( )	Topography 2-4%
Site Suitable	Yes	(✓)	No	( )	Depth to Water Table 10+
					Rock or other impervious formations Bare Naked

Lot Area 1 Acre

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by H.E. Houston

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY J C Moore

COMMENTS: What a mess! System installed very deep due to improper placement. 2 Lines originally installed uphill & were corrected by stone addition and division middle trench over. Also tank was raised to assist in correction.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: Ralph Sheets RS DATE 7/10/87

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold