DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: 101856
COUNTY: 4763-79-0894

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: TIMOTHY & SUSAN EDWARDS APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: 1.67
LOCATION OF SITE: _____ PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL CLASS & LTAR
1	10% LSS	0-3"	scl, wk gr	fr, ns, np, msp	KEEP REPAIR SHALLOW GRAV OR LP PAVE ABOVE				PS .25
		3-24"	scl, SAME, wk gr	fr, ns, np, msp					
		24-36"	cl, med, abk	fr, ss, sp, scp					
		36-48"	cl, med, abk	fr, ss, sp, scp	? many mottles				
2	10% LSS	0-3"	scl, wk, gr	fr, ns, np, msp	few distinct mottles at 24-30"	>48"			PS .25
		3-30"	cl, med, abk	fr, ss, sp, scp					
		30-48"	cl, med, abk	fr, ss, sp, scp					
3	10% LSS	0-3"	scl, wk, gr	fr, ns, np, msp		>48"			PS .35
		3-32"	cl, med, sbk	fr, ss, sp, scp					
		32-48"	saprolite	fr, ns, np, msp					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	YES	YES
System Type(s)	GRAV CURT	GRAV CURT OR LP PAVE
Site LTAR	.25	.25

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: L. COOK
OTHER(S) PRESENT: _____