IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System — G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Bean Bldg Co DATE 1-21-76 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION St Clair Dr

S. R. No. _____

SUBDIVISION NAME Shannon Acres LOT NO. 318 SECTION OR BLOCK NO. _____

House (4) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 4 No. Bathrooms 4

Garbage Disposal Unit	Yes	(4)	No	( )
Auto. Dishwasher	Yes	(4)	No	( )
Auto. Wash. Machine	Yes	(4)	No	( )
Site Suitable	Yes	(4)	No	( )

Lot Area 45,000


Character & Porosity of Soil Clay Type Soil - Yellow Clay

Percolation Rate 60 min

Topography Slopes to East

Depth to Water Table 25+

Rock or other impervious formations None



Plot of System

Size of Tank 1500 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 1080 Linear Ft. 360

Depth of Stone in Lines 10"

Water Supply: Individual (4)

Public ( )

Installed by Hall Septic Tank Co

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY _____ DATE 1/21/76

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold