DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ *of* ___
PROPERTY ID #: 4764968398
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Gene Pickens / Pickens Enterprises, Inc. APPLICATION DATE _____
ADDRESS: Lot #11 SKYLAND - Bill Francis DATE EVALUATED: _____
PROPOSED FACILITY: 3bR Home PROPOSED DESIGN FLOW (.1949): 360 gpd PROPERTY SIZE: 0.65 Ac.
LOCATION OF SITE: _____ PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☑ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	LR 3%	0-9	gr L	vfr sap	~ YR Ch 4	>48			PS 0.25
		9-24	Abk C	fi sap					
		24-48+	sbk C	fi sap					
2	L/R 3%	0-11	gr L	vfr sap	~ 15	>48	-	-	PS 0.275
		11-18	sbk C	fi sap					
3	L 2-4%	0-8	gr L	vfr sap	>18	>48	-	-	PS 0.275
		8-18	sbk cl	vfr sap					
		18-42	sbk C	fi sap					
		42-48+	sbk C+Sap	fi sap					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	II	II
Site LTAR	0.275	0.25

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: TCH
OTHER(S) PRESENT: _____

COMMENTS: 1310 360 3bR 48 PS