IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Rodgers Bycik DATE 7/7/78 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION E. Broad St. Ext., T.R. into Brookmede, corner of Brookmede and Nuckelsdam S. R. No. _____

SUBDIVISION NAME _____ LOT NO. 8 SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2½

Garbage Disposal Unit	Yes (✓)	No ( )	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes ( )	No ( )	

Lot Area _____

Character & Porosity of Soil Cecil clay & Sandy loam
Percolation Rate mod - slow
Topography 2-10%
Depth to Water Table high
Rock or other impervious formations possible seasonal high water table



Size of Tank 1250 Gals.
Nitrification Field:
No. of Lines 4
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 16" +
Water Supply: Individual ( )
Public (✓)

Installed by Eddie Yountz

IMPROVEMENTS PERMIT BY _____

COMMENTS: Extra stone depth added - system in sandy soil above a 2:1 clay

CERTIFICATE OF COMPLETION BY Andrew E. Causey DATE 7/19/78

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold