DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: 106869
COUNTY: 4765 46-8461

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: FLEETWOOD APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: _____
LOCATION OF SITE: R RIVER GREEN LOT 8 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL. CLASS & LTAR
1	1 & 2 ALLUVIAL SOILS	0-32	SL/scl mix wk gr	f ns sp smp	→ light colors yellow mottles mixed in at 32"	H2O mark at 4 GRADE CUT ABOVE OLD ISSUE			PS .25
		32-48"	c/scl mix wk gr	f ss sp smp					
3 ⑧	LSS 4 0/0	0-3"	scl wk gr	f ns sp smp	NEEDS FRENCH DRAIN				PS .2
		3-24	c med able	f s p smp					
		24-48	" "	" "	→ light yellow soils with red streaks very few coarse Z mixed in				
4 ⑤	LSS 4 0/0	0-3"	scl wk gr	f ns sp smp	NEEDS FRENCH DRAIN				PS .2
		3-32"	c med able	f s p smp					
		32-48"	c med able	f s p smp	→ yellow/red streaks very few coarse Z mixed in				
⑥									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	1 TRAN PANEL	1 P PANEL
System Type(s)	YES	YES
Site LTAR	.2	.2

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: L. LOVE
OTHER(S) PRESENT: C. THOMPSON