DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Larry Lambert Floodplain APPLICANT: Larry Lambert
ADDRESS: _____ APPLICATION DATE: 11/29/01 DATE EVALUATED: 12/6/01
PROPOSED FACILITY: 3BR mH/com PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: .6
LOCATION OF SITE: Hwy 64 W, Right on Rd @ Riverside Drive #24 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

Lot #24

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL. CLASS & LTAR
1	2% L Ridge	0-2	Scl	SS SP					PS .3
		2-28	cl mstfi	cp					
		28-40	cl wsbk fi	sp					
		40-48	cl mw wsbk	ss sp					
2	2% Ridge	0-2	scl wsbk fi	ss sp	FOW 24" w/in 24"				PS .3
		2-40	cl msbk fi	sp					
		40-48	cl msbk fi/vfi	sp					
3	5% Linear	0-3	scl msbk	fi ss sp					PS .3
		3-24	cl msbk	fi sp					
		24	cl w/ms wsbk	fi ss					
		30-48	cl w/sap [illegible]	fi ss sp					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	Gravity Conv.	50% Reduct
Site LTAR	.3	.3

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: William [illegible]
OTHER(S) PRESENT: _____