DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: Rupert Julie Parks APPLICANT: Same
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
PROPOSED FACILITY: 3BR Home PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: 1.0
LOCATION OF SITE: in Crowl PROPERTY RECORDED: X
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | OTHER PROFILE FACTORS .1943 SOIL DEPTH | OTHER PROFILE FACTORS .1956 SAPRO CLASS | OTHER PROFILE FACTORS .1944 RESTR HORIZ | PROFIL. CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | Linear 6% | 0-6 | scl | | | | | | PS .3 |
| | | 6-21 | cl | | | | | | |
| | | 21-38 | cl w/ mica | | | | | | |
| | | 38+ | scl w/ many sap | | | | | | |
| 2 | Linear 3% | 0-4 | Sacl | Strop SEx | | | | | PS .3 |
| | | 4-18 | cl | Sp | | | | | |
| | | 18:40 | cl w/ Sap | Strop | | | | | |
| | | 40-48 | Sap | Sl (SE) | | | | | |
| 3 | Linear 4% | 0-6 | scl | | | | | | PS .3 |
| | | 6-16 | cl | | | | | | |
| | | 16-36 | cl w/ Sap | | 16" Brn Mottles | | | | |
| | | 36-48 | Sapp | | | | Keep | | |
| 4 | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | PS | PS |
| System Type(s) | 2 row 2 trench | Bottom 25% Rock |
| Site LTAR | .3 | .3 |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: Bill Johnson
OTHER(S) PRESENT: _____