646

1058 350
2017 263

J.C. Moore
Certified Operator #985357
Maintenance Report Form

Name and Location of System
Alexander Cano
117 East Gate Drive
Statesville, N.C.
28625

Date of Inspection
3-4-10

Permit Number
156313

County
Iredell

System Classification
IV-A

Name and Address of "ORC"
J.C. Moore
1227 Troutman Drive
Statesville, NC 28625

Name and Address of Owner
Same

Phone: (704) 873-2171

Phone: 704 609 3214

Legend: S-Satisfactory, M-Marginal, U-Unsatisfactory
N-not evaluated, N/A-Nonapplicable

SEPTIC TANK AND PUMP TANK
NO Risers accessible
S Signs of Infiltration
S Structurally Sound
S Landscape Position
YES Filter Cleaned

PUMP
YES Pump present and operating
33 Design GPM
33 Actual GPM
100 % Efficiency
YES High water alarm operating properly
S Pipework in good condition
S Control panel in good condition
S Control floats operating properly
S Straps and float tree
S Effluent free and clear of solids

DRAIN FIELD
S No effluent surfacing
S Surface water diverted
S Line cover maintained properly
S Protected from traffic
S Distribution devices operating properly
S Repair area reserved

COMMENTS

Compliant ✓ Noncompliant ___
Signature J.C. Moore

Date 3-4-10
LOW PRESSURE PIPE SYSTEM
S Turnups, cleanouts, valves located and protected
S Laterals free of excess solids
YES Laterals flushed
Pressure Heads

	Design head	Adjusted head
Line 1	2'	2'
Line 2	2'	2'
Line 3	2'	2'
Line 4	2'	2'
Line 5	2'	2'
Line 6	2'	2'

J.C. Moore
Certified Operator #985357
Maintenance Report Form

Name and Location of System
Alexander Cano
117 Eastgate Drive
Statesville, N.C.
28625

Date of Inspection
9-22-10

Permit Number
156313

County
Iredell

System Classification
IV - A

Name and Address of "ORC"
J.C. Moore
1227 Troutman Drive
Statesville, NC 28625

Name and Address of Owner
Same

Phone (704) 873-2171

Phone: 704 609 3214

Legend: S-Satisfactory, M-Marginal, U-Unsatisfactory
N-not evaluated, N/A-Nonapplicable

Checked Inlet Side of Septic Tank - No foam layer + about 4" sludge - good condition. Does not need Pumping

SEPTIC TANK AND PUMP TANK
No Risers accessible
S Signs of Infiltration
S Structurally Sound
S Landscape Position
~~S~~ Filter Cleaned
No
PUMP
Yes Pump present and operating
33 Design GPM
33 Actual GPM
100 % Efficiency
Yes High water alarm operating properly
S Pipework in good condition
S Control panel in good condition
S Control floats operating properly
S Straps and float tree
S Effluent free and clear of solids

DRAIN FIELD
S No effluent surfacing
S Surface water diverted
S Line cover maintained properly
S Protected from traffic
S Distribution devices operating properly
S Repair area reserved

COMMENTS

Compliant ✓ Noncompliant ___
Signature J.C. Moore

Date 9-22-10
LOW PRESSURE PIPE SYSTEM
S Turnups, cleanouts, valves located and protected
S Laterals free of excess solids
Yes Laterals flushed
Pressure Heads

	Design head	Adjusted head
Line 1	1'	2'
Line 2	2'	2'
Line 3	2'	2'
Line 4	2'	2'
Line 5	2'	2'
Line 6	2'	2'

J.C. Moore
Certified Operator #985357
Maintenance Report Form

Name and Location of System
Alexander Cano
117 Eastgate Dr.
Statesville, N.C.
28625

Date of Inspection
3-4-11

Permit Number
156313

County
Iredell

System Classification
LV - A

Name and Address of "ORC"
J.C. Moore
1227 Troutman Drive
Statesville, NC 28625

Name and Address of Owner
Same

Phone: (704) 873-2171

Phone: 704 609 3214

Legend: S-Satisfactory, M-Marginal, U-Unsatisfactory
N-not evaluated, N/A-Nonapplicable

SEPTIC TANK AND PUMP TANK
No Risers accessible
S Signs of Infiltration
S Structurally Sound
S Landscape Position
Yes Filter Cleaned

PUMP
Yes Pump present and operating
33 Design GPM
33 Actual GPM
100 % Efficiency
Yes High water alarm operating properly
S Pipework in good condition
S Control panel in good condition
S Control floats operating properly
S Straps and float tree
S Effluent free and clear of solids

DRAIN FIELD
S No effluent surfacing
S Surface water diverted
S Line cover maintained properly
S Protected from traffic
S Distribution devices operating properly
S Repair area reserved

COMMENTS

Compliant ✓ Noncompliant ___
Signature J.C. Moore

Date 3-4-11

LOW PRESSURE PIPE SYSTEM
S Turnups, cleanouts, valves located and protected
S Laterals free of excess solids
Yes Laterals flushed

Pressure Heads

	Design head	Adjusted head
Line 1	2'	2'
Line 2	2'	2'
Line 3	2'	2'
Line 4	2'	2'
Line 5	2'	2'
Line 6	2'	2'

MOORE'S ENVIRONMENTAL SERVICES
1227 TROUTMAN DRIVE
STATESVILLE, NC 28625
HOME: (704) 873-2171
CELL: (704) 902-1122 FAX: (704) 873-9928

Dear Alexander Cano :

According to my records, your Type IV-A septic system at 117 Eastgate Dr Statesville is past due for a renewal on the maintenance contract for the time period of Sept 2011 to Sept 2012.

I will need to be contacted by you if you would like to renew your maintenance contract with my company. If I don't hear from you by oct 15, 2011, I will assume you have made other arrangements and no longer need my services.

According to the North Carolina Department of Environmental Health law #15A.NC, Admin. Code #18A.1961, I am required to notify the Iredell Health Department that I am no longer the operator for your system if you choose not to renew with my company.

Thank you for your past business and hopefully we can continue to do business in the future.

Sincerely,

J. C. Moore

J. C. Moore
NC Registered Sanitarian (Cert. #372)
Subsurface System Operator (Cert. #985357)
NC Onsite Wastewater Inspector (Cert. #12331)

J.C. Moore
Certified Operator #985357
Maintenance Report Form

Name and Location of System
Alexander Cano
117 Eastgate Dr.
Statesville, N.C.
28625

Date of Inspection
10-14-11

Permit Number
156313

County
Iredell

System Classification
IV-A

Name and Address of "ORC"
J.C. Moore
1227 Troutman Drive
Statesville, NC 28625

Name and Address of Owner
Same

Phone: (704) 873-2171

Phone: 704 609 3214

Legend: S-Satisfactory, M-Marginal, U-Unsatisfactory
N-not evaluated, N/A-Nonapplicable

SEPTIC TANK AND PUMP TANK
ND Risers accessible
S Signs of Infiltration
S Structurally Sound
S Landscape Position
ND Filter Cleaned

PUMP
YES Pump present and operating
33 Design GPM
33 Actual GPM
100% Efficiency
YES High water alarm operating properly
S Pipework in good condition
S Control panel in good condition
S Control floats operating properly
S Straps and float tree
S Effluent free and clear of solids

Date 10-14-11
LOW PRESSURE PIPE SYSTEM
S Turnups, cleanouts, valves located and protected
S Laterals free of excess solids
YES Laterals flushed
Pressure Heads

	Design head	Adjusted head
Line 1	2'	2'
Line 2	2'	2'
Line 3	2'	2'
Line 4	2'	2'
Line 5	2'	2'
Line 6	2'	2'

DRAIN FIELD
M No effluent surfacing lines are wet but not surfacing
S Surface water diverted
S Line cover maintained properly
S Protected from traffic
S Distribution devices operating properly
S Repair area reserved

COMMENTS

Compliant ✓ Noncompliant ___
Signature J.C. Moore

MOORE'S ENVIRONMENTAL SERVICES
1227 TROUTMAN DRIVE
STATESVILLE, NC 28625
HOME: (704) 873-2171
CELL: (704) 902-1122 FAX: (704) 873-9928

Alexander Cano
117 Eastgate Drive
Statesville, NC

Dear Mr. Cano:

On October 14, 2011, I did an inspection and maintenance service on your low pressure Type IV-A septic system at the above address as agreed upon in our contract. I mailed you an invoice along with the written report on this inspection. I have not received payment for this period of September 2011 to September 2012. The six month inspection is now due, but I will not be doing this service because of the nonpayment. In accordance with the payment agreement in our contract I am now terminating this contract. According to the state sewage rules, you will be responsible for finding another licensed operator for your system. I will be sending a notification to the Iredell County Health Department to inform them that I am no longer your operator.

Thank you for the opportunity to serve you in this matter.

Sincerely,

J. C. Moore
NC Registered Sanitarian (Cert. #372)
Subsurface System Operator (Cert. #985357)
NC Onsite Wastewater Inspector (Cert. #12331)