42901

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

14449

OWNER OR CONTRACTOR BUTTKE DAIRY DATE 4/10/92 PERMIT NO. 12G-1-A-16x15

PHONE: Business _____ Home _____

LOCATION US 21 N, TL TABOR ROAD, TL HENKLE FARM ROAD, 1ST MH ON (R)

S. R. No. _____

SUBDIVISION NAME HARMONY HILLS LOT NO. 16, 15 SECTION OR BLOCK NO. _____


House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	
			Rock or other impervious formations	EXISTING

Lot Area 228 x 333

_____ Basement with Plumbing _____ Basement without Plumbing ___✓___ No Basement



Plot of System

Size of Tank _____ Gals.

Nitrification Field: EXISTING

No. of Lines _____

Sq. Ft. _____ Linear Ft. _____

Depth of Stone in Lines _____

Water Supply: Individual (✓) WELL

Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: SYSTEM DESIGNED FOR HOUSE & MH, HOUSE HAS BURNED & IS BEING REPLACED W/ MH.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: STEVE HEDRICK DATE 4/10/92

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold