IREDELL COUNTY HEALTH DEPARTMENT

10737

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Harvey J. Todd DATE Feb 6, 90 PERMIT NO. 4T-A-45

PHONE: Business _____ Home _____

LOCATION 115-21N. TR 2383 (Shennandoah Rd.) X Creek
~1 mile TL private gravel rd. on Right S. R. No. _____


SUBDIVISION NAME JL Bowles property of Tolbert Est LOT NO. 19420 Combined SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2
Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site ~~Suitable~~ LPS Yes (✓) No ( )
Lot Area ~1 Ac.

Character & Porosity of Soil PS clay
Percolation Rate 40 4
Topography 26 20
Depth to Water Table 44 none obs.
Rock or other impervious formations _____

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 4
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by Tim Smith

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: LPS Repair Area

CERTIFICATE OF COMPLETION BY _____ DATE Feb 6, 90

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

10727

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Harvey Jo Todd DATE Nov. 20, '89 PERMIT NO. 4J-A-45

PHONE: Business _____ Home _____

LOCATION 115-21 N. TR 2383 (Shennville Rd) x Creek
~1 mile TL private gravel road ~3rd on Right

SUBDIVISION NAME J Bowles property & Tolbert Estate LOT NO. 19 & 20 Combined SECTION OR BLOCK NO. _____ S. R. No. _____

House ( ) Mobile Home (✓) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site ~~Suitable~~ PS	Yes (✓)	No ( )	

Lot Area ~1 AC.

Character & Porosity of Soil clay
Percolation Rate ~1.4
Topography ~6%
Depth to Water Table 4'+
Rock or other impervious formations none obs.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 4
Sq. Ft. 200 Linear Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: ✗ Harvey Jo Todd

IMPROVEMENTS PERMIT BY David R. Henson, R.S

COMMENTS: LPS Repair
10' LOT LINE
Follow contour. 30" trench bottom depth. Pull plumbing out at ground level at upper end of mobile home.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold