4770 09 47 17

08357

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Roger Dale Compton DATE Aug 15, '88 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 115-21 N. TR 2383 (Shinnville Rd) x Creek ~ 1½ mi. on Rt. _____ S. R. No. _____

SUBDIVISION NAME Jolene Talbert Estate Tract LOT NO. 32 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 1

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes ( ) No (✓)

Auto. Wash. Machine Yes (✓) No ( )

Site ~~Suitable~~ PS. Yes (✓) No ( )

Lot Area 5 Ac.

Character & Porosity of Soil Clay


Percolation Rate 2.35

Topography 6-10%

Depth to Water Table 44

Rock or other impervious formations none obs.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 2

Sq. Ft. 690 + Linear Ft 230+

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by Dobson

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DRH

COMMENTS: Well not down.

CERTIFICATE OF COMPLETION BY D R Hinson, RS DATE 8-15-88

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

08357

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Roger Dale Compton DATE July 28, '88 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 115-21 N TR 2383 (Shinnville Rd.) x Creek ~ 1½ miles on Rt. _____ S. R. No. _____

SUBDIVISION NAME former Tolbert Estate LOT NO. 32 SECTION OR BLOCK NO. _____


House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 1

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes ( ) No (✓)
Auto. Wash. Machine Yes (✓) No ( )
Site ~~Suitable~~ OK Yes (✓) No ( )
Lot Area 5 Ac.

Character & Porosity of Soil clay
Percolation Rate 2.35
Topography 6-10%
Depth to Water Table 4'+
Rock or other impervious formations none obs.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 2
Sq. Ft. 690 Linear Ft. 230
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: Roger D. Compton

IMPROVEMENTS PERMIT BY [illegible] RS

COMMENTS: Follow contour with drainfield. Install at a maximum depth of 36" to bottom of ditch (24" cover) and a minimum depth of 24" to bottom of ditch (12" cover). May use drop boxes if desired.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold