DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Tamara Sheridan APPLICATION DATE ___
ADDRESS: ___ DATE EVALUATED: 7/8/03
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: Acre
LOCATION OF SITE: ___ PROPERTY RECORDED: ___
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	CV N 7-9%	0-11	sbk - hel mk.	FI. S SP.	PS				
		12-25	Fr sbk - cl	FR SS SP.					
		26-33	FR sbk/GR l SAP	Fr. SS SP					
		34-48	MFr GR SAP	VFR SS SP			PS		.25
2	CV 9%	0-7	wk sbk c *mk	VFI S - P					
		8-23	sbk c SAP.	FI S - SP					
		24-	Rock		k	k			
3	LS 8%	0-9	sbk - cl	FI S - SP					
		10-26	Fr sbk cl	FR SS - SP					
		27-35	M sbk/GR l SAP	FR SS - SP					.25
		36-48	MFr GR SAP	VFR SS - SP					.25
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	S	S
System Type(s)	Typ 3	Typ 3
Site LTAR	.25	.25

OTHER FACTORS (.1946): Non slope
SITE CLASSIFICATION (.1948): PS - 30" trench depth.
EVALUATED BY: [signature]
OTHER(S) PRESENT: ___

COMMENTS: Convex contour - 7-9% grade - 36" trench depth.