IREDELL COUNTY HEALTH DEPARTMENT

APPENDIX H

SITE EVALUATION

(Ground Absorption Sewage Disposal)

OWNER: James A. Mason

DATE REQUESTED: 12-9-80

ADDRESS:

PLAT NO.:

COUNTY: Iredell

LOT SIZE: 1+ ACRE

LOCATION OF SITE: 1100 ft. 1113 State Rd. (Diagonally Across from Road 1114

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS 2-6% U	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1 clay)	S (PS) clay U	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey soils)	S (PS) Subangular Blocky U	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	(S) PS 48+ U	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, rock)	(S) None observed PS U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	(S) None observed PS U	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S PS Mod U	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION*	PS			
SOIL SERIES	Cecil			

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc.)

Recommendations/Comments: See Comments Many scattered quartz rock on surface

Described By: Fred Clemmer

Title: SE

Date: 12-9-80

DHS Form 2601 (2/77)
Sanitation