Department of Environment, Health, and Natural Resources
Division of Environmental Health
On-site Wastewater Section

Sheet: 1 OF 1
Property ID: 4771-34-2105
Lot #:
File #: REPAIR
AppID:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Owner: CHRIS MCNEELY
Address: 132 CANTEBERRY DR. SALISBURY, NC 28144
Applicant: SAME
Proposed Facility: SFR Design Flow (.1949) 480
Date Evaluated: 11/22/2011
Location of Site: 1508 OSTWALT AMITY RD.
Property Size: 70 AC
Water Supply: [ ] Public [X] Individual [X] Well [ ] Spring [ ] Other
Property Recorded: YES
Evaluation Method: [X] Auger Boring [ ] Pit [ ] Cut
Type of Wastewater: [X] Sewage [ ] Industrial Process [ ] Mixed

PROFILE #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941 .1941 Structure/ Texture	.1941 Consistence Mineralogy	b PROFILE FACTORS .1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
AB 1	LINEAR 3%	0-11	SL,W,GR	NS,NP	COMMON Y/BR	48"	NA	48+	.2
		11-30	C,M,SBK	SS,SP					
		30-48	C,W	STICKEY					
AB 2	LINEAR 3%	0-10	SL,W,GR	NS,NP	COMMON Y/BR	38"	NA	38"	.2
		10-30	C,W,SBK	STICKEY					
		30-38	CL,W,SBK	SS,SP	YELLOW ROCK				
		38+	ROCK						
AB 3	LINEAR 3%	0-12	SL,W,GR	NS,NP	COMMON Y/BR	48"	NA	48+	.2
		12-48	C,W,SBK	STICKEY					
AB 4	LINEAR 3%	0-12	SL,W,GR	NS,NP	COMMON Y/BR	56"	NA	56+	.2
		12-41	C,W,ABK	STICKEY					
		41-56	SCL,M,SBK	SS,SP					

Description	Initial System	Repair System
Available Space (.1945)		PS
System Type(s)		G-25%
Site LTAR		.2

Other Factors (.1946):
Soil Evaluation By: BEN ALDRIDGE
Others Present:
Site Classification (.1948): PS
Site Evaluation By: BEN ALDRIDGE
Others Present: