DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Tabitha Dillard
ADDRESS: _____
PROPOSED FACILITY: _____ APPLICATION DATE _____
LOCATION OF SITE: _____ PROPOSED DESIGN FLOW (.1949): 360gpd DATE EVALUATED: 9-1-06
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY SIZE: 0.9-6
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed PROPERTY RECORDED: _____

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	Headslope	0-18	1 gr scl			48			.25
		18-32	1 sbk c	fs/sp SE					
		32-48	1 sbk cl						
		40-48	1 abk/sbk scl	yellow mottling low chroma					
2		0-24	1 sbk scl		10YR 7/2 few 7.5YR	40			.25 shallow trench
		24-40	1 sbk cl	s/p					
		40-48	1 abk c	fs/p SE					
3	4% sideslope	0-10	1 sl gr sl			48			.3
		10-40	1 sbk cl	fr ss/sp SE					
		40-48	1 sbk scl	few incl. sap					
4		0-14	1 sl gr sl			48			.3
		14-40	1 sbk cl	fr ss/sp/SE					
		40-48	1 sbk scl	inc. sap					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

COMMENTS: _____

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: J. McNeille
OTHER(S) PRESENT: _____