DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET ___ OF ___

PROPERTY I.D.#: 16784
PROPERTY RECORDED: 3N-1-A-293
COUNTY: Iredell

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Horn Bldg. Co. OWNER: AGENT: PHONE:
ADDRESS: APPLICATION DATE: DATE EVALUATED: 8-10-93
PROPOSED FACILITY:
PROPERTY SIZE:
LOCATION OF SITE: Briarcliff Dr.
WATER SUPPLY: On-Site Well ___ Comm. Well ___ Public ✓ Other ___ EVAL. METHOD: Auger Boring ✓ Pit ___ Cut ___

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	2-4% L	0"-3"	scl / gr	1:1 / vfr	P.S.	NA	P.S.	NA	.35
		3"-37"	c / sbk	1:1 / fr					
		37"-↑	saprolite						
2	2-4% L	0"-4"	scl / gr	1:1 / vfr	P.S.	NA	P.S.	NA	.35
		4"-40"	c / sbk	1:1 / fr					
		40"-↑	saprolite						
3									
4									
5									

AVAILABLE SPACE (.1945): 5 SITE CLASSIFICATION (.1948): P.S. SITE LONG-TERM ACCEPTANCE RATE: .35 gpd/ft²
EVALUATED BY: Michael J. Dennis OTHER(S) PRESENT:
COMMENTS: Install system shallow (no deeper than 24" to trench bottom)