12118

# IREDELL COUNTY HEALTH DEPARTMENT

38613

## (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR CHARLES BAKER DATE 4/26/91 PERMIT NO. 11C2-A-33

PHONE: Business _____ Home _____

LOCATION 64E, TL SAIN RD, TR 3RD PAVED ROAD, TO STOP SIGN, TL 3RD HOUSE ON (L) S. R. No. _____

SUBDIVISION NAME FOX CREEK LOT NO. 18 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes (✓) No ( )

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Lot Area 1.7 AC

Character & Porosity of Soil PS

Percolation Rate 4 GPD / FT²


Topography 6-10%

Depth to Water Table 74'

Rock or other impervious formations SAPROLITE AT 36"

ACP 2/22/91

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement




Plot of System

Size of Tank 1250 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 900 Linear Ft. 300

Depth of Stone in Lines 12"

Water Supply: Individual ( )

Public (✓)

Installed by DAVID YOUNTS

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY J. C. MOORE

COMMENTS: _____

CERTIFICATE OF COMPLETION BY STEVE HENDRICK DATE 4/26/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold