DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: 4776629757
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

1 39778

OWNER: Spears Hendary
ADDRESS: _____ #16
PROPOSED FACILITY: Hse PROPOSED DESIGN FLOW (.1949): _____
LOCATION OF SITE: Swamp Crossing

APPLICATION DATE _____
DATE EVALUATED: _____
PROPERTY SIZE: _____
PROPERTY RECORDED: _____

WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☑ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 10%	0-12	SCWSBL	SSSPSHPL					3
		12-27	CWSBL	SSSPSHPL					
		27-50	CMSBL	SSPSHPFi	modeling				
2	L 10%	0-16	SCWSBL	SSSPSHPFr					3
		16-40	CMSBL	SSSPSHPL	modeling				
		40-50	CMSBL	SSPSHPFi	- Start of SHP Ht 55" L/S				
3	L 10%	0-19	SCWSBL						0
		19-50	CMSBL	SSSPSHPFi	modeling - SHP indicator Rate Seepage Mills				.25
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	1440	1440
System Type(s)		
Site LTAR	.25	.25

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): B
EVALUATED BY: BKuykendall
OTHER(S) PRESENT: _____

COMMENTS: _____