DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

109 788

OWNER: BUTTICE DAIRY APPLICANT: 4776-79-4569
ADDRESS: ___ APPLICATION DATE: ___ DATE EVALUATED: ___
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): ___ PROPERTY SIZE: ___
LOCATION OF SITE: ___ PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL. CLASS & LTAR
1	8% LSS	0-8"	sl wk gr	fr ns np slp	few yellow mottles not restr. 2				PS .25
		8-32	c med sbk	fr s,p,sl sp					
		32-48"	c med sbk	fr s,p,sl sp					
2	8% LSS	0-8"	sl wk gr	fr ns np slp					PS .25 .3
		8-36"	c med sbk	fr s,p,sl sp					
		36-49"	c med sbk Sat. mottles	fr s p sl sp					
3	8% LSS	SAME AS HOLE 1							PS .25
4	4%	SAME AS HOLE 1 & 3							PS .25

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	4	4
System Type(s)	CONV (RA)	CONV/ PUMP 25%
Site LTAR	.25	.25

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: LOCKE
OTHER(S) PRESENT: MR. BUTTICE