DEPARTMENT OF ENVIRONMENT, HEALTH & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

DRAFT

SHEET 1 OF 1
PROPERTY I.D.#: 11L-2-A-49
DATE: 2/12/96
COUNTY: Iredell

SOIL SITE EVALUATION FOR ON-SITE WASTEWATER SYSTEM

APPLICANT: Anthony Turner
ADDRESS:
OWNER ✓ AGENT: PHONE: 871-8605
APPLICATION DATE: 2/12 DATE EVALUATED 2/12/96
PROPOSED FACILITY: Mobile Home 3 Br
PROPERTY SIZE: 125x215'
LOCATION OF SITE: Coducced Subd Phase II Lot 49
WATER SUPPLY: On-site Well ___ Comm. Well ___ Public ___ Other ___ EVAL. METHOD: Auger Boring ✓ Pit ___ Cut ___

PROFILE #	.1940 LANDSCP POS./ SLOPE(%)	HORIZON DEPTH (IN.)	.1941 a[1] TEXTURE	.1941 a[2] STRUCTURE	.1941 a[3] MINEROLOGY	MATRIX COLOR	MOTTLE COLOR	OTHER PROFILE FACTORS
1	6%	0-2	Sandy Clay					.1942 Wetness Cond. - None
		2-38	Clay	Tight Clay	1:1		N/A	.1943 Depth/.1956 Sapr. - None 38"
								.1944 Restrictive Hori. - None
								.1948 Profile Class. - PS
								Profile LTAR - 0.3
2	6%	0-1	Sandy Clay					.1942 Wetness Cond. - None
		1-39	Clay	Blocky	1:1		N/A	.1943 Depth/.1956 Sapr. - None 39"
								.1944 Restrictive Hori. - None
								.1948 Profile Class. - PS
								Profile LTAR - 0.3
3								.1942 Wetness Cond. -
								.1943 Depth/.1956 Sapr. -
								.1944 Restrictive Hori. -
								.1948 Profile Class. -
								Profile LTAR -
4								.1942 Wetness Cond. -
								.1943 Depth/.1956 Sapr. -
								.1944 Restrictive Hori. -
								.1948 Profile Class. -
								Profile LTAR -

AVAILABLE SPACE (.1945) S OTHER FACTORS (.1946) ___ SITE CLASSIFICATION (.1948) PS
SYSTEM TYPE Conv Gravity w/ Repair LONG-TERM ACCEPTANCE RATE(S) 0.3
EVALUATED BY: [signature] OTHER(S) PRESENT: Anthony Turner
COMMENTS:

0026119