IREDELL COUNTY HEALTH DEPARTMENT

12841

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR W P BREWER DATE 7/22/91 PERMIT NO. 2H-A-41

PHONE: Business _____ Home _____

LOCATION US21 N TL BEL-AIRE DR JUST BEFORE HARMONY CHIROPRACTIC, TR DARLENE LANE 2ND LOT ON (L) S. R. No. _____


SUBDIVISION NAME HARMONY MEADOWS LOT NO. 6 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 2
Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )
Lot Area 0.1664 AC

Character & Porosity of Soil PS
Percolation Rate .4 GPD/FT2
Topography 6-8% LS
Depth to Water Table > 4'
Rock or other impervious formations NONE

Basement with Plumbing ____ Basement without Plumbing ____ No Basement (✓)



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 600 Linear Ft. 200
Depth of Stone in Lines 12"
Water Supply: Individual ( )
Public (✓)

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: Dennis Gallihen

IMPROVEMENTS PERMIT BY STEVE HEDRICK

COMMENTS: _____

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold