IREDELL COUNTY HEALTH DEPARTMENT 37977

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C) PART OF

11813
OWNER OR CONTRACTOR ROBERT HUDGINS, JR DATE 3/22/91 PERMIT NO. 12D-A-46

PHONE: Business 872-4250 Home

LOCATION OLD MOCKSVILLE RD, TR VAUGHN MILL, CROSS BRIDGE 1ST DRIVE TO (L) S. R. No.

SUBDIVISION NAME LOT NO. SECTION OR BLOCK NO.


House (✓) Mobile Home ( ) Business ( ) Other

No. Bedrooms 3 No. Bathrooms 2 Character & Porosity of Soil PS
Garbage Disposal Unit Yes ( ) No ( ) Percolation Rate .4 GPD / FT²
Auto. Dishwasher Yes (✓) No ( ) Topography 6-10%
Auto. Wash. Machine Yes (✓) No ( ) Depth to Water Table >4'
Site Suitable Yes (✓) No ( ) Rock or other impervious formations SCATTERED ROCK

Lot Area AMPLE

✓ Basement with Plumbing ___ Basement without Plumbing ___ No Basement

ACP 2/19/91



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by DAVID YOUNTS

I understand and agree to install septic tank system as specified on this Improvements Permit.
⊗ WELL

Signed:

IMPROVEMENTS PERMIT BY STEVE HEDRICK / GLENN FOX, JR

COMMENTS:

CERTIFICATE OF COMPLETION BY STEVE HEDRICK DATE 3/22/91

EXISTING SYSTEM CHECKED BY: DATE

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold