SOIL SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

4789 13 2019

ROBER TEMPLETON — APPLICANT: SAME

S: 590 MOCKSVILLE HWY, STVL, 28625 — APPLICATION DATE: _____ — DATE EVALUATED: 7-13-98

ED FACILITY: 3BR MH — PROPOSED DESIGN FLOW (.1949): 360 — PROPERTY SIZE: 0.7 ACRE

ON OF SITE: RIMROCK ESTATES LOT #7 — PROPERTY RECORDED: _____

SUPPLY: ☐ Private ☑ Public ☐ Well ☐ Spring ☐ Other _____

ATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut

F WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
L 6%	0-6	GR / SCL	FR	—	—	PS	—	PS 0.3
	6-42	SBK / C	FI					
	42-48	SAPROLITE MIX						
L 6%	0-5	GR / SCL	FR	—	—	PS	—	PS 0.3
	5-42	SBK / C	FI					
	42-48	SAPROLITE						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ilable Space (.1945)	PS	PS
tem Type(s)	CONV. GRAV.	CONV. GRAV.

OTHER FACTORS (.1946): NONE

SITE CLASSIFICATION (.1948): PS

EVALUATED BY: S. HEDRICK

OTHER(S) PRESENT: _____