IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System G. S. Chapter 130-Article 13C)

Bobby Anderson

OWNER OR CONTRACTOR Bell Anderson DATE 22 June 75 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 21 N to Harmony - TR on 901 - 1st gravel past Mt View Lake to RW 2132 on Right. 1st grave 1mi - Home on Right. S. R. No. _____


SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1½

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	Sand Clay
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	fine
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	Slope to left of lot
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	ok
			Rock or other impervious formations	ok

Lot Area 1.11 acre



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 625 Linear Ft. 250
Depth of Stone in Lines 10"

Water Supply: Individual (✓)
Public ( )

Installed by Roy Lenty

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY WM Howard DATE 23 June 75

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold