DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

4798-05-2647

Sheet 1 of 1
PROPERTY ID #:
COUNTY: Ire

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Roger Cleary
APPLICANT: Fleetwood Homes of Troutman
ADDRESS: 151 Eastgate Dr. Statesville 28625
APPLICATION DATE: 12-1-03
DATE EVALUATED: 1-7-04
PROPOSED FACILITY: 3br/2ba
PROPOSED DESIGN FLOW (.1949): 360
PROPERTY SIZE: 1.00 ac
LOCATION OF SITE: From Jane Sowers Rd © Old Mocksville ®Vaughn Mill®Society
PROPERTY RECORDED: Yes
WATER SUPPLY: ☐ Private ☑ Public ☐ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL. CLASS & LTAR
1	L 5%	0-3	WK SBK SCL	VFR S/SP SEXP	—	>48	—	—	PS .3
		3-30	MO SBK C	FR S/P SEXP					
		30-48	MO SBK C+SAP	FR S/SP SEXP					
2	L 5%	0-2	WK SBK SCL	VFR SS/SP SEXP	—	36	N/E	—	PS .3
		2-10	MO SBK C	FR S/P SEXP					
		10-36	WK SBK C+SAP	VFR SS/SP SEXP					
		36+	SL M SAP	—					
3	L 5%	0-16	WK SBK CL	FR S/P SEXP	—	>48	—	—	PS .25
		16-48	MO SBK/ABK C	FI S/P SEXP					
4	L 7%	0-7	WK SBK SCL	VFR SS/SP SEXP	—	21	N/E	—	CLV N/A
		7-21	MO SBK/ABK C+SAP	FI S/P SEXP					
		21+	SL M SAP	—					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	Conv Gravity	Conv. Gravity
Site LTAR	.25	.25

OTHER FACTORS (.1946): No
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Chris Shuler
OTHER(S) PRESENT: Ed Osborne - Fleetwood

LEGEND

use the following standard abbreviations

LANDSCAPE POSITION	GROUP	SOIL TEXTURE	CONVENTIONAL .1955 LTAR	LPP .1957 LTAR	MINERALOGY/ CONSISTENCE	STRUCTURE
CC (Concave Slope)	I	S (Sand)	1.2 - 0.8	0.6 - 0.4	NEXP (Non-expansive)	G (Single Grain)
CV (Convex Slope)		LS (Loamy Sand)			SEXP (Slightly Expansive)	M (Massive)
D (Drainage Way)					EXP (Expansive)	CR (Crumb)
DS (Debris Slump)	II	SL (Sandy Loam)	0.8 - 0.6	0.4 - 0.3		GR (Granular)
FP (Flood Plain)		L (Loam)				SBK (Subangular Blocky
FS (Foot Slope)						ABK (Angular Blocky)
H (Head Slope)	III	SI (Silt)	0.6 - 0.3	0.3 - 0.15		PL (Platy)
L (Linear Slope)		SICL (Silty Clay Loam)				PR (Prismatic)
N (Nose Slope)		CL (Clay Loam)				
R (Ridge)		SCL (Sandy Clay Loam)			MOIST	WET
S (Shoulder Slope)		SLC (Silt Loam Clay)				
T (Terrace)					VFR (Very Friable)	NS (Non-sticky)
	IV	SC (Sandy Clay)	0.4 - 0.1	0.2 - 0.05	FR (Friable)	SS (Slightly Sticky)
		SIC (Silty Clay)			FI (Firm)	S (Sticky)
					VFI (Very Firm v. Very Sticky)	VS (Very Sticky)
		O (Organic)	None		EFI (Extremely Firm)	NP (Non-plastic)
						SP (Slightly Plastic)
						P (Plastic)
						VP (Very Plastic)

NOTES

HORIZON DEPTH	In inches below natural soil surface
DEPTH OF FILL	In inches from land surface
RESTRICTIVE HORIZON	Thickness and depth from land surface
SAPROLITE	S(suitable) or U(unsuitable)
SOIL WETNESS	Inches from land surface to free water or inches from land surface to soil colors with chroma 2 or less - record Munsell color chip designation
CLASSIFICATION	S (Suitable), PS (Provisionally Suitable), or U (Unsuitable)

Evaluation of saprolite shall be by pits.

Long-term Acceptance Rate (LTAR): gal/day/ft²

Show profile locations and other site features (dimensions, reference or benchmark, and North).

