IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Rocky Hill Baptist Church DATE 22 Sept 75 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Hwy 115 N to Rd 1583 on left past Central Nursery - Approx 2.5 miles - Church on left. S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House ( ) Mobile Home ( ) Business ( ) Other Addition Classroom - 200

No. Bedrooms _____ No. Bathrooms _____

Garbage Disposal Unit	Yes ( )	No ( )
Auto. Dishwasher	Yes ( )	No ( )
Auto. Wash. Machine	Yes ( )	No ( )
Site Suitable	Yes ( )	No ( )

Character & Porosity of Soil Coul Cly loam
Percolation Rate more
Topography _____
Depth to Water Table ok
Rock or other impervious formations possible rock at Bdk

Lot Area 2 acres



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 562½ Linear Ft. 225
Depth of Stone in Lines _____
Water Supply: Individual ( )
Public ( )

Installed by Hoyle Brothers

IMPROVEMENTS PERMIT BY W. M. Howard

COMMENTS: Existing syste for church. Educational Building being added. 2 additional bathrooms. Existing syste has functional capacity in part of syste give trouble, it must be repaired & specifications of Iredell County Health Dept.

CERTIFICATE OF COMPLETION BY W M Howard DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold