DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY I.D. #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: Wayne Benfield APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 10-4-87
PROPOSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): 2 bdrm PROPERTY SIZE: _____
LOCATION OF SITE: Lot 5 Foothills Rd. PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | 1940 LAND SLOPE POSITION/ SLOPE % | HORIZON DEPTH (IN) | SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE | 1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR | 1943 SOIL DEPTH | 1956 SAPRO CLASS | 1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | L-H 10% | 0-27 | ssab, bnar cl fr sp-sspsp | | | | | | P 03 |
| | | 27-46 | wk sab bnar pl fi sss p-sp | | | | | | |
| | | | wk we rock/sap | | | | | | |
| | | | pedominantly soil | | | | | | |
| 2 | L 8% | 0-26 | sab rd cl | fr sssp sap | | | | | P5 .034 |
| | | 26-46 | wk sab pbk | fr sp sap | | | | | |
| | | | few wk fine tap | | | | | | |
| 3 | L 9% | 0-18 | gr, bnar, cl bn sil | fr sp-sap | | | | | P5 .3 |
| | | 18-55 | sab pcl | fr sssp sap | | | | | |
| | | 28-55 | wk sab pbrk | fr sp sap | | | | | |
| 4 | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____