IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Ethel Beatty DATE Sept. 1, 1977 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 115 N. T.L. on SR 1583 T.L. on SR. 1585 (beside Ballou Works) 1st trailer on Rt. S. R. No. _____


SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	Cecil clay loam	
Auto. Dishwasher	Yes ( )	No (✓)	Percolation Rate	—	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	Rolling	
Site Suitable	Yes ( )	No ( )	Depth to Water Table	unk.	
			Rock or other impervious formations	unk.	

Lot Area acreage



Plot of System

Size of Tank existing Gals.
Nitrification Field:
No. of Lines existing
Sq. Ft. _____ Lineal Ft. _____
Depth of Stone in Lines _____
Water Supply: Individual (✓)
Public ( )

Installed by James Hutness

IMPROVEMENTS PERMIT BY _____

COMMENTS: Inspection of existing system revealed no malfunction at present time. Existing trailer to be replaced by double-wide m.h.

CERTIFICATE OF COMPLETION BY Harold R. Hinson DATE Sept. 1, 1977

CONSTRUCTION MUST COMPLY WITH ALL

Location of the proposed bathroom addition does not appear to impact the existing on-site septic system.**NOTE: _____

Health Dept. Copy: White Inspection Dept. Co

REHS
Date: 12-15-11
ICHD-Environmental Health Division

4-2030