## IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Jom Dial DATE 10-30-73 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Hwy 115 Above Central School - T.L. on Love Valley Rd # 1583. T.L. 1st Drive Past Rd 1622. Bear to R When Drive Forks - Trailer in Woods

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____ S. R. No. _____


House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1

| | | |
|---|---|---|
| Garbage Disposal Unit | Yes ( ) | No (✓) |
| Auto. Dishwasher | Yes ( ) | No (✓) |
| Auto. Wash. Machine | Yes (✓) | No ( ) |
| Site Suitable | Yes (✓) | No ( ) |

Lot Area 8 Acres

Character & Porosity of Soil Clay
Percolation Rate Perk Test made
Topography Steel Slope to back
Depth to Water Table Low
Rock or other impervious formations Shale rock found.




Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 2
Sq. Ft. 585 Linear Ft. 234
Depth of Stone in Lines 10"
Water Supply: Individual (✓)
Public ( )

Installed by Lawrence Pearson

IMPROVEMENTS PERMIT BY E. A. Stevenson

COMMENTS: Layout had to be changed due to rock formations underground. Shale rock in bottom of ditch.

CERTIFICATE OF COMPLETION BY E. A. Stevenson DATE 11-5-73

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold