07951

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK, IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR CLARENCE D. WHITE DATE 2-25-88. PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Hwy 115 N - T.L. on Mt. View Rd. - T.R. on Love Valley Rd. - T.L. on McCanless Trail before stream - house on (R) 1/8 mi. S. R. No. _____

SUBDIVISION NAME LOVE VALLEY LOT NO. _____ SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 1

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil Gravelly Sandy Loam
Auto. Dishwasher	Yes ( )	No (✓)	Percolation Rate 4 gal/sq. ft.
Auto. Wash. Machine	Yes (✓)	No ( )	Topography 2-6% lot
Site Suitable	Yes (✓)	No ( )	Depth to Water Table surface rock

Lot Area Ample Rock or other impervious formations _____

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 2
Sq. Ft. 600 Linear Ft. 200
Depth of Stone in Lines 12"

Water Supply: Individual ( )
Public (✓)

Installed by Donald Lackey.

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Steve Brown

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Steve Brown DATE 2-25-88.

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold