IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Charles Dyson DATE 12-4-74 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Hwy 115 N. T.L. on Love Valley Rd #1583 – T.R. at Mountain View Church #1586 - Cross Stream. Trailer on R. S. R. No. _____


SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 1

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes ( ) No (✓)
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes ( ) No ( )
Lot Area 3/4 Acre

Character & Porosity of Soil Marginal - Yellowish Clay
Percolation Rate _____
Topography Slight Slope
Depth to Water Table Unk
Rock or other impervious formations None



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 625 Linear Ft. 250
Depth of Stone in Lines 10"
Water Supply: Individual (✓)
Public ( )
From Spring
Installed by Lackey Bro

IMPROVEMENTS PERMIT BY _____

COMMENTS: Poor Soil - Lines are deep.

CERTIFICATE OF COMPLETION BY E. A. Stevenson DATE 12-4-74

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold