IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System — G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Charles Rupard DATE 26 May 75 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Hwy 115 to Liniji Mill Rd. on left. (4598)
do 1.3 mi on left past Taylor Springs Church. S. R. No. _____

SUBDIVISION NAME Taylor on left Lewis Stream NO. _____ SECTION OR BLOCK NO. _____


House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1½

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes ( )	No (✓)	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Character & Porosity of Soil Cecil Clay
Percolation Rate 1 inch
Topography Slope & creek
Depth to Water Table 10'
Rock or other impervious formations Rock ledge

Lot Area _____



Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 616 Linear Ft. 231
Depth of Stone in Lines 10"
Water Supply: Individual ( )
Public ( )
Spring
Installed by James Thornton

IMPROVEMENTS PERMIT BY _____

COMMENTS: Wet work - changed locations - let work year - family got sick last day - had to abandon - have done to work. Ditch appx. 8" wide. Slightly short of county minimum but best that could be done at location.

CERTIFICATE OF COMPLETION BY Russ Howard DATE 26 May 75

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold