DEPARTMENT OF HEALTH AND HUMAN SERVICES
DIVISION OF PUBLIC HEALTH, ENVIRONMENTAL HEALTH SECTION
ON-SITE WATER PROTECTION BRANCH

Sheet 1 of 1
PROPERTY ID #: 4813575599
COUNTY: Iredell

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM
(Complete all fields in full)

OWNER: Cecil Marlowe
ADDRESS: 1004 Linney's Mill Rd
PROPOSED FACILITY: SFD
PROPOSED DESIGN FLOW (.1949): 240
LOCATION OF SITE: 115 to Linneys mill to Bowles Store Rd
WATER SUPPLY: ☒ Private ☐ Public ☒ Well ☐ Spring ☐ Other N/A
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

APPLICATION DATE: 5-30-15
DATE EVALUATED: 6-15-15
PROPERTY SIZE: 0.963ac
PROPERTY RECORDED: Yes

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 7%	0-8	Gr SCL	fr SE	PS	PS	N/A	N/A	PS ,3
		8-32	SBK C	fr SE					
		32-48	WSBK BC	fi/fr SE					
2	L 8%	0-9	Gr SCL	fr SE	PS	PS	N/A	N/A	PS ,3
		9-34	SBK C	fi SE					
		34-48	WSBK BC	fi/fr SE					
3	L 10%	0-6	Gr SCL	fr SE	PS	PS	N/A	N/A	PS ,3
		6-30	SBK C	fi SE					
		30-48	WSBK BC	fi/fr SE					
4	L 10%	0-7	Gr SCL	fr SE	PS	PS	N/A	N/A	PS ,3
		7-31	SBK C	fi SE					
		31-48	WSBK BC	fi/fr SE					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	III	III
Site LTAR	,3	,3

OTHER FACTORS (.1946): PS
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: H. Snow
OTHER(S) PRESENT:

COMMENTS: