01890

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Howard L. Gaither DATE 9-12-84 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 11.5 N - Post Central School - Rt on SR 1871 (Duckers Grove Rd) 1st Right 1 Mile Down on Right S. R. No 1871

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

Double Wide

House ( ) Mobile Home (✓) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Lot Area 1 Acre

Character & Porosity of Soil Clay-Non-Porous
Percolation Rate 55 min 1" in pool
Topography 2 - 6% Slope
Depth to Water Table 12'
Rock or other impervious formations Scattered Rock

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System SR 1871

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 2
Sq. Ft. 720 Linear Ft. 240
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by James Hartness

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Allen Fox Jr DATE 9/12/84

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold