42002

IREDELL COUNTY HEALTH DEPARTMENT

on terminal

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

13874 14H-A-46

OWNER OR CONTRACTOR DONALD HARMON DATE 1/7/92 PERMIT NO. 14N-A-46

PHONE: Business _____ Home _____

LOCATION NC 115 N, TR BRUCE ROAD, TR TUCKER'S GROVE ROAD, 1ST MH ON (L)

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____ S. R. No. _____

House ( ) Mobile Home (✓) Business ( ) Other _____ ⊗ WELL

No. Bedrooms 3 No. Bathrooms 2


Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Lot Area AMPLE

Character & Porosity of Soil PS
Percolation Rate .5 GPD / FT2
Topography 6-8% NS
Depth to Water Table > 4'
Rock or other impervious formations SCATTERED ROCK

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement

TP 10/7/91



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 2
Sq. Ft. 720 Linear Ft. 240
Depth of Stone in Lines 12"

Water Supply: Individual (✓) WELL
Public ( )

Installed by JOHN MENSCER

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY STEVE HEDRICK

COMMENTS: _____

CERTIFICATE OF COMPLETION BY STEVE HEDRICK DATE 1/7/92

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold