DEPARTMENT OF ENVIRONMENT, HEALTH & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

DRAFT

SHEET 1 OF 1
PROPERTY I.D.#: 15J-A-67
DATE: 9-20-95
COUNTY: REDELL

SOIL SITE EVALUATION FOR ON-SITE WASTEWATER SYSTEM

APPLICANT: THEODORE G. SUMMERVILLE
ADDRESS: 7962 UNITY CH. RD. DENVER, NC 28037
OWNER ✓ AGENT: PHONE: (704) 483-6902
APPLICATION DATE: 9-7-95 DATE EVALUATED 9-20-95
PROPOSED FACILITY: 3BR D/W MH
PROPERTY SIZE: 2.25 ACRES
LOCATION OF SITE: NC 115 N, TR FLETCHER RD, LOT ON LEFT BEFORE ZEB ROAD
WATER SUPPLY: On-site Well ✓ Comm. Well ___ Public ___ Other ___ EVAL. METHOD: Auger Boring ✓ Pit ___ Cut ___

PROFILE #	.1940 LANDSCP POS./ SLOPE(%)	HORIZON DEPTH (IN.)	.1941 (a)(1) TEXTURE	.1941 (a)(2) STRUCTURE	.1941 (a)(3) MINEROLOGY	MATRIX COLOR	MOTTLE COLOR	OTHER PROFILE FACTORS
1	L	0-6	L	GR	1:1 / VFR			.1942 Wetness Cond. - S
	4%	6-48	C	MASBK	1:1 / FR			.1943 Depth/.1956 Sapr. - S
								.1944 Restrictive Hori. - S
								.1948 Profile Class. - PS
								Profile LTAR - 0.35
2	L	0-8	L	GR	1:1 / VFR			.1942 Wetness Cond. - S
	6%	8-48	C	MASBK	1:1 / FR			.1943 Depth/.1956 Sapr. - S
								.1944 Restrictive Hori. - S
								.1948 Profile Class. - PS
								Profile LTAR - 0.35
3								.1942 Wetness Cond. -
								.1943 Depth/.1956 Sapr. -
								.1944 Restrictive Hori. -
								.1948 Profile Class. -
								Profile LTAR -
4								.1942 Wetness Cond. -
								.1943 Depth/.1956 Sapr. -
								.1944 Restrictive Hori. -
								.1948 Profile Class. -
								Profile LTAR -

AVAILABLE SPACE (.1945) S OTHER FACTORS (.1946) NONE SITECLASSIFICATION (.1948) PS
SYSTEM TYPE CONV. GRAVITY LONG-TERMACCEPTANCE RATE(S) 0.35 GPD/FT2
EVALUATED BY: S. HEDRICK OTHER(S) PRESENT: LEROY TEMPLETON
COMMENTS:

00235