DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of _
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Michael Allen APPLICANT: Same
ADDRESS: 1051 Rear Creek Ct Rd Hwy 9 APPLICATION DATE: 3-26-01 DATE EVALUATED: 4/17/01
PROPOSED FACILITY: 3BR House & Shop PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: 3.25
LOCATION OF SITE: PROPERTY RECORDED: N
WATER SUPPLY: ☒ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL. CLASS & LTAR
1		0-7"	SC s	fr NS NP NE					LTS
		7-21"	sc w/rock sbk	fi ss sp SE					
		21"	Quartz Rock	—					
2		0-7	SL s	fr NS NP NE					PS
		7-13	SC sbk	fi S P SE					.3
		13-24	sc w/sap sbk	fi ss sp se					
		24-48	Sap (2) Rock	fr ss ns NE					
3		0-9	SL s	fr NS NP VE sp					PS
		9-24	SC sbk	fi					.3
		24-48	sc w/sap sbk	fr					
4		0-5"	SL (g)	fr ss NP VS sp					PS
		5-28"	sc sbk	fi ss s SE					.3
		28"-48"	sc w/sap sbk	fi ss s se					
	Repair								

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)		
Site LTAR	.3	.3

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: Bill Johnson
OTHER(S) PRESENT: _____