IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Claude Fulk DATE Aug 2, 1977 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION I 77N T.L. on 901 T.R. on SR. 1807 T.L. on SR 1805 ~2.5 mi. on Rt. S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


Existing House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1½

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes ( )	No (✓)	
Auto. Wash. Machine	Yes ( )	No (✓)	
Site Suitable	Yes (✓)	No ( )	

Character & Porosity of Soil Cecil Clay Loam
Percolation Rate _____
Topography 2% wy respect to N. lines
Depth to Water Table Tank scattered rock observed
Rock or other impervious formations _____

Lot Area ~1 Acre



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 2
Sq. Ft. 600 Linear Ft. 200
Depth of Stone in Lines 10" +
Water Supply: Individual ( )
Public ( )
Spring
Installed by G'ill Diggers

IMPROVEMENTS PERMIT BY R. Hinson

COMMENTS: New installation for existing house with no previous approved sewage disposal.

CERTIFICATE OF COMPLETION BY David R. Hinson DATE Aug 2, 1977

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold