IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION 38328
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

11460

OWNER OR CONTRACTOR CARL E SHAVER DATE 4/11/91 PERMIT NO. 16D-H-22

PHONE: Business _____ Home _____

LOCATION I-77N, TL ON TOMLIN MILL, TR JENNINGS ROAD, TL WEISNER ROAD, TL CURRENT RD, HOUSE ON (R) S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 4 No. Bathrooms 3 1/2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	PS
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	.46 GPD / FT²
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2-6 %
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	10'
			Rock or other impervious formations	SCATTERED ROCK

Lot Area 1.422 AC

TP 5/11/90

✓ Basement with Plumbing ____ Basement without Plumbing ____ No Basement



Plot of System

Size of Tank 1250 Gals.

Nitrification Field:
No. of Lines 4
Sq. Ft. 1200 Linear Ft. 400
Depth of Stone in Lines 12"

Water Supply: Individual (✓) WELL
Public ( )

Installed by JOHN MENSGER

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY GLENN FOX, JR

COMMENTS: _____

CERTIFICATE OF COMPLETION BY STEVE HEDRICK DATE 4/11/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold