01753

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

01753

OWNER OR CONTRACTOR Randy Simmerson DATE 07-19-84 PERMIT NO.

PHONE: Business Home

LOCATION I-77 N, T.L. on 901 to Union Grove, T.L. on SR 1852 (Sloan Mill Rd), T Rt on SR 1857 - Go Approx ½ mi, T L on Private Rd, 1/2 mile on R

SUBDIVISION NAME LOT NO. S. R. No. SECTION OR BLOCK NO.

House ( ) Mobile Home (✓) Business ( ) Other

No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Lot Area 2 acres

Character & Porosity of Soil CLASS IV


Percolation Rate 0.4 gal/sq ft/day

Topography 2-6% Slope

Depth to Water Table 10+

Rock or other impervious formations Scattered Rock PARENT MATERIAL

___ Basement with Plumbing ___ Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 2

Sq. Ft. 720 Linear Ft. 240

Depth of Stone in Lines 12"

Water Supply: Individual ( )

Public (✓)

Installed by Paul Fogg

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed:

IMPROVEMENTS PERMIT BY Glenn Fox, Jr.

COMMENTS: Rain in upper line before covered

CERTIFICATE OF COMPLETION BY Jerry L Sides DATE 07-19-84

EXISTING SYSTEM CHECKED BY: DATE

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold