IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Gary Goodin DATE June 26, 1977 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION I 77N . T.L. on 901 T.R. on SR. 1532 1st chicken house on left. S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House ( ) Mobile Home ( ) Business (●) Other Chicken house

No. Bedrooms _____ No. Bathrooms 1

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes ( ) No (✓)
Auto. Wash. Machine Yes ( ) No (✓)
Site Suitable Yes (✓) No ( )

Character & Porosity of Soil Cecil clay
Percolation Rate —
Topography 2%
Depth to Water Table unk
Rock or other impervious formations none observed

Lot Area 26 acres



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 625 Linear Ft. 250
Depth of Stone in Lines 10"+
Water Supply: Individual (✓)
Public ( )

Installed by G & M Diggers

IMPROVEMENTS PERMIT BY Andrew E. Causey

COMMENTS: _____

CERTIFICATE OF COMPLETION BY David R. Hinson DATE July 26, 1977

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold